

HABS  
WASH  
17-RENT  
ID-

Historic American Buildings Survey

INDEX TO PHOTOGRAPHS

Longacres (Longacres Park), Paddock Club  
1621 SW 16th Street  
Renton  
King County  
Washington

HABS No. WA-201-4

John Stamets, photographer 1993

<u>HABS No.</u>	<u>Description</u>
WA-201-4-1	Paddock Club. East side. Jockey Building is on left and north addition to Clubhouse is on the right. Camera pointed WSW. (May 1993)
WA-201-4-2	Paddock Club. West side and parking lot. Camera pointed ESE. (May 1993)
WA-201-4-3	Paddock, path and hedge on east side. Camera pointed N. (August 1993)
WA-201-4-4	Paddock and path on north side. Camera pointed SE. (August 1993)
WA-201-4-5	Paddock horse stalls on south wall. Camera pointed SW. (August 1993)
WA-201-4-6	Interior of Paddock Club on lower level, including column with sculptural relief detail by artist Susan Pascal. Camera pointed S. (July 1993)
WA-201-4-7	Interior of Paddock Club on upper level. Camera pointed N. (July 1993)
WA-201-4-8	Photocopy of photograph. (Original is No. PI-23497 in the Seattle Post-Intelligencer Collection at the Museum of History and Industry (MOHAI), Seattle, WA. A print from the original negative can be ordered from MOHAI).  A 1939 view of the Paddock as viewed from the Clubhouse. The Paddock barn, partially visible on right, was later moved to the south (approximately to the end of the outer row of cars in distance) where it became the Mechanics Shop. Three views of the Mechanics Shop taken in 1993 are seen in photos WA-201-8-1, WA-201-8-2 and WA-201-8-3.